



**U.S. AIR FORCE**

# **15 March 2004 ACTION ITEM #5**

**DESCRIPTION:** Currently, the supply systems do not allow parts in AWP status to be ordered as MICAP.

**ACTION REQUIRED:** Need new supply systems to allow bases to order AWP bits and pieces as MICAP.

4 May 04 – Add: Identify our requirements and provide to the developers of the new supply system.

**OPR:** Mr Colquitt Lawrence

**SUSPENSE DATE:** **30 Apr 04**

(Changed on 4 May 04) 31 Jul 2004

**STATUS:** Open